अण्डमान तथा निकोबार प्रशासन विद्युत विभाग अधिशासी अभियन्ता कार्यालय दक्षिण अण्डमान मण्डल, हैडो पोर्ट ब्लेयर - 744102 टेलि:03192-232549,फैक्सस:03192-232549



Andaman & Nicobar Administration Electricity Department Office of the Executive Engineer South Andaman Division Haddo, Port Blair- 744102 Tel: 03192-232549, Fax: 03192-232549

फै.सं.F.No.EE/SA/Tech/1-28/174

पोर्ट ब्लेयर/Port Blair, दिनांक/Dated: 02/06/2018

प्रेस विज्ञप्ति/PRESS NOTE

It is brought to the notice of general public/consumers and Government departments under South Andaman Division that the incessant rain and high velocity prevailing wind in these islands led to interrupted power supply at many places in South Andaman area due to falling of trees, snapping of conductors, damage of electric poles etc. The departmental staffs are working round the clock on war footing to restore the power supply within shortest possible time. The general public are also requested not to touch damaged poles and conductors found fallen down if any. Report on such incidents may be made to the knowledge of nearest site office of Electricity Department or Police station immediately.

The inconvenience caused to consumers is regretted. It is requested to bear with the department and cooperate for early restoration of power supply.

अधिशासी अभियन्ता (द.अ.)- Executive Engineer(SA)